

<u>Weeks 5 and 6:</u> These past two weeks our team has gotten closer to finishing the chassis of our car. We have just recently completed the halo on the car. This completion was not without some struggles though. It took a few tries but we finally figured out the right way to cut it to make the halo fit perfectly. We have also started cutting our front axle and welded many parts on the chassis.



Justin with what has been completed so far as of 10/19/10



Justin, Jesse, and Amy measuring out the lengths of the halo

<u>Next few weeks</u>: Our team will be working on the front and rear axle. We are working on making fewer mistakes by taking more precise measurements to make sure we are as accurate as possible.